DocuSign Envelope ID: C91CC3D2-D1DC-42C4-BACC-2A7247F021C9



__SGS__ este compania lider mondial in inspectie, verificare, testare si certificare. Recunoscuti ca si referinta globala pentru calitate si integritate, noi furnizam servicii __inovative__ si __solutii__ pentru fiecare sector al industrie de mediu. Reteaua noastra globala de birouri si laboratoare, pe langa echipa noastra dedicata, ne permite se raspundem la solicitari, oricand si oriunde apar.

RAPORT DE ANALIZE

NUMAR RAPORT:

50000284-9

12.09.2023

EMIS DE:

SGS ROMANIA S.A.

38, Calea Serban Voda 040212,
Bucharest Romania

CLIENT:

LINDE GAZ ROMANIA S.R.L.

A. Imbroane Nr. 9, 300136, Timisoara, Romania

Comanda: **9300587907**

Redactat astazi: 12.09.2023

SGS Romania S.A.

Intocmit,
Mihai Muresan

DocuSigned by:
1475C14C41814C4...

Verificat,
Iulian Rusu

DocuSigned by:
FF4E355BAC384BB...

DocuSign Envelope ID: C91CC3D2-D1DC-42C4-BACC-2A7247F021C9

INDEX

CUPRINS RAPORT

1. SCOPUL ANALIZELOR.....3

2. METODOLOGIE 3

3. REZULTATE.....4

DocuSign Envelope ID: C91CC3D2-D1DC-42C4-BACC-2A7247F021C9

1. SCOPUL ANALIZELOR

SGS Romania a fost desemnata de Linde Gaz Romania S.R.L. pentru a furniza urmatoarele servicii:

- Prelevare si analize proba apa uzata prelevata pentru monitorizarea calitatii factorilor de mediu conform prevederilor autorizatiei de mediu.

Denumirea locatiei si instalatiei de unde au fost prelevate probele: Ultimul canal inainte de evacuare in retea canalizare municipala (camin racord limita proprietate).

Adresa: Linde Gaz Romania – Strada Avram Imbroane Nr. 9, Timisoara, Judetul Timis (conform declaratie client)

Data prelevarii: 21.07.2023.

2. METODOLOGIE

Proba a fost prelevata de reprezentantul laboratorului.

Proba a fost analizata in laboratorul SGS Romania, acreditat RENAR conform SR ISO 17025:2018, cu numarul LI 713.

DocuSign Envelope ID: C91CC3D2-D1DC-42C4-BACC-2A7247F021C9

3. REZULTATE

Cod proba laborator		**780 EHS**	**Valori limita conform AIM 2/07.12.2016**	
Identificare proba		**Apa uzata proba momentana**		
Matrice proba		**Apa uzata**		
Data prelevarii		**20.07.2023 Ora:10:00**		
Data primirii probei in laborator		**21.07.2023 Ora:12:00**		
Prelevat de:		**Client**		
Parametru	Unitate masura	**Rezultat**		
1. pH SR EN ISO 10523:2012				
pH	pH unit	7,4 (temp.det=23,8 ^{0}C)	6,5-8,5	
2. Substante extractibile in solvent SR 7587:1996				
Substante extractibile in solvent	mg/L	<20(#6,0)	30	
3. Consum chimic de oxigen SR ISO 6060:1996				
Consum chimic de oxigen CCOCr	mg O_2/L	55,48	500	
4. Consum biochimic de oxigen dupa 5 zile SR EN 5815-1:2020				
Consum biochimic de oxigen – CBO5	mg O_2/L	20,27	300	
5. Materii in suspensie SR EN 872:2005				
Materii in suspensie	mg/L	8,0	350	

9. Conditii de mediu

Temperatura medie	^{O}C	24		
Presiune barometrica	hPa	1010,0		
Umiditate atmosferica medie	U_R%	64		

Rezultate conform Raport de Incercare 780EHS/31.07.2023

DocuSign Envelope ID: C91CC3D2-D1DC-42C4-BACC-2A7247F021C9

NOTE

(*) Incercarile marcate NU sunt acoperite de acreditarea RENAR. Pentru detalii suplimentare vă rugăm să solicitaţi Certificatul de Acreditare la sgs.romania@sgs.

(#) Valorile marcate sunt in afara limitelor acreditate de raportare ale incercarii.

ND Nu sunt date disponibile

Rezultatele din acest raport nu sunt negociabile.

Materialul ramas din proba (e) va fi eliminat, dupa o saptamana , daca nu se precizeaza altfel. (Se aplica conditii)

Alte observatii:

Incertitudinea se raporteaza la solicitarea clientului.

DISCLAIMERS / EXONERARE DE RASPUNDERE

This document is issued by the company under its general conditions of service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. The client's attention is drawn to the limitation of indemnification and jurisdiction issues defined therein./ *Acest document este emis de companie cu respectarea Conditiilor generale privind serviciile, disponibile la cerere si accesibile la http://www.sgs.com/terms_and_conditions.htm. Se atrage atentia clientului asupra limitarilor de despagubiri si problemelor de jurisdictie definite in Conditii*

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. / *Detinatorul acestui document este informat ca informatiile continute reflecta constatarile Companiei numai de la momentul interventiei sale si in limitele instructiunilor de la Client, daca exista. Responsabilitatea Companiei este numai fata de Clientul sau si acest document nu exonereaza partile dintr-o tranzactie sa-si exercite toate drepturile si obligatiile din documentele tranzactiei. Orice modificare neautorizata, falsificare sau falsificare a continutului sau formei acestui document este ilegala si faptuitorii pot fi urmariti penal conform legii*.

Unless otherwise stated the results shown in this analytical test report refer only to the tested sample(s) collected on a specific date, and time, and ambient conditions, as mentioned in the report./ *Daca nu este altfel specificat, rezultatele din acest raport de incercare se refera numai la probele analizate, care au fost colectate la o anumita data, ora si conditii de mediu, asa cum este mentionat in raport.*

This Report refers exclusively to the state of the goods at the time and place of inspection only, which was carried out to the best of our knowledge and ability.

Acest raport nu poate fi reprodus decat integral / This report must not be reproduced, except in full